

Note:
0.5 sec GF delay setting does not comply with IEEE C37.17.

AC-PRO-II G.F. Rev 1.02 05/12/2015

AC-PRO-II Ground Fault Time Current Curve